

## Yazon, Edwin (CC)

---

**From:** Yazon, Edwin (CC)  
**Sent:** November 17, 2020 9:27 AM  
**To:** 'Dave Howes'  
**Subject:** RE: Shelby Tubes- RC2 - Miller Environmental

Good morning Dave,

The results of the testing achieves compliance with the Licence requirements, therefore please be advised that the HDPE liner can now be installed at the SW corner of RC2. Please provide a written report regarding the installation, QA/QC and engineering oversight of the HDPE liner installation. Further, please be advised that the SW corner of RC2 cannot be used until a written approval is received from the Environment Officer.

Sincerely,

Edwin Yazon  
(431) 335-2554

---

**From:** Dave Howes <daveh@millerenvironmental.mb.ca>  
**Sent:** November 16, 2020 3:28 PM  
**To:** Yazon, Edwin (CC) <Edwin.Yazon@gov.mb.ca>  
**Subject:** RE: Shelby Tubes- RC2 - Miller Environmental

Hi Edwin,

Please see attached the updated hydraulic conductivity report for the SW corner of RC2. No value was obtained for the first sample as a preferential flow path caused it to begin failing immediately and the test was ended.

We are working on updating our facility map to include RC3. I'll send it as soon as it is completed. The sample locations (page 8) and pictures (page 7) are identified in the attached report. If you have any other questions, please let me know. Thanks.

Dave